, Helston TR13

APARTMENT REFURB

Saturday, March 04, 2017

Prepared For

Identified 19 Issues

KNUMar

Kevin Millar BSc (Hons) MCIOB

Hawthorn Estates Ltd





Internal Apartment

Hawthorn Estates Ltd Hallway



Kitchen First Floor

Hawthorn Estates Ltd

Old disconnected boiler and new boiler needed and possibly move elsewhere to create more kitchen space.



Kitchen First Floor

Hawthorn Estates Ltd New Kitchen and white goods



Electric Supply And Board

Hawthorn Estates Ltd

New fuse consumer unit needed including removal of the old coin meter and new one added including electrical certificate for the property.



First Floor Room 1

Hawthorn Estates Ltd

Redecoration and carpets including Removal of office equipment.



First Floor Room 2

Hawthorn Estates Ltd

Redecorate and carpets and removal of office furniture.



Stairwell

Hawthorn Estates Ltd

Redecorate and carpets plus new bannister rail.



Room 1 Second Floor

Hawthorn Estates Ltd Redecorate and carpets



Room 2 Second Floor
Hawthorn Estates Ltd
Redecorate and carpets



Room 3 Second Floor
Hawthorn Estates Ltd
Redecorate and carpets



Bathroom Second Floor

Hawthorn Estates Ltd Redecorate and replace electric shower with new including new vinyl flooring



Toilet Second Floor
Hawthorn Estates Ltd
Redecorate and replace vinyl



Heating Cupboard
Hawthorn Estates Ltd



Water Damage Room 2 Second Floor
Hawthorn Estates Ltd
Appears dry



Water Damage Room 1 Second Floor
Hawthorn Estates Ltd
Water Damage appears dry



Windows

Hawthorn Estates Ltd

Windows generally satisfactory and would benefit from painting internally and externally. Kitchen and Second Floor Room 1 need replacement. If the front Windows need replacement for future these would come under the local conservation issues.



External Access to the apartment

Hawthorn Estates Ltd Steel fire escape access



Roof Space

Hawthorn Estates And



Roof Space

Hawthorn Estates Ltd

Roof Space in a good condition including roof timbers and steel work. Extra bagged insulation would improve thermal efficiency.