



External Windows Painted



External Windows Painted



External Windows Painted



Roof Photo



Gutters Cleaned



External Windows Painted



External Windows Painted



External Windows Painted



External Windows Painted



External Windows Painted



External Windows Painted

Helston TR13

REFURBISHMENT

Friday, June 02, 2017

Prepared For

Identified 55 Issues



Kevin Millar BSc (Hons) MCIOB

Hawthorn Estates Ltd

HAWTHORN



E S T A T E S



New Kitchen



New Kitchen



Cooker



Washer




Understairs Cupboard And Fridge Freezer



New LED Kitchen Light



Top Floor Room




Upstairs Room Windows Internal




Top Floor Room



Top Floor Room Window Internal



Stairs



Top Floor Room



Top Floor Room



Old Cylinder Cupboard



Top Floor Toilet



Top Floor Room



Upstairs Room



Top Floor Landing



Top Floor Landing



Bathroom Floor New



Top Floor Landing



First Floor Room Window Internal



First Floor Room



First Floor Room Window Internal




First Floor Hallway



First Floor Room



First Floor Hallway Entrance Looking In



Electric Consumer Unit Cupboard



First Floor Room



First Floor Room



First Floor Room



Gas Ready For Meter



New Gas Pipe To Boiler




New Consumer Unit



New Consumer Unit



External Vent Pipe For Boiler



New 1kW Sub Meter



External Windows Painted



External Windows Painted



Gutter and Soffit Cleaned



External Windows Painted



External Windows Painted



External Windows Painted



External Windows Painted
